

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046 USA

Date: 2 October 2023

Ref: Cover letter (C2PC)

FCC ID: IPH-03910

To whom it may concern:

Changes to IPH-03910 include passive component value changes to improve the manufacturing process, component substitution to reduce cost, and enclosure changes to reduce cost. Minor PCB layout changes accompany a few of the component substitutions. Moreover, these hardware changes do not affect the SAR and/or RF field strength limits previously calculated.

There is a decrease in output power for Wi-Fi 2.4 GHz in the ax mode.

Sincerely,

William H. Pertner

Compliance Engineering Team Leader Garmin

International, Inc.

Garmin International, Inc

Address: 1200 East 151st Street, Olathe, Kansas, 66062 Contact

Person: Bill Pertner Tel.: 913-440-5471

Email: Bill.Pertner@garmin.com

William H Pertin