


Test setup photographs




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04095  
Test: 210310  
Test to: CFR47 15C, RSS-210  
File: A04095 Short Term Conf TSup

SN's: 3361094336, 3361094128  
FCC ID: IPH-04095  
IC: 1792A-04095  
Date: September 20, 2021  
Page 1 of 4






Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04095  
Test: 210310  
Test to: CFR47 15C, RSS-210  
File: A04095 Short Term Conf TSup

SN's: 3361094336, 3361094128  
FCC ID: IPH-04095  
IC: 1792A-04095  
Date: September 20, 2021  
Page 2 of 4





Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04095  
Test: 210310  
Test to: CFR47 15C, RSS-210  
File: A04095 Short Term Conf TSup

SN's: 3361094336, 3361094128  
FCC ID: IPH-04095  
IC: 1792A-04095  
Date: September 20, 2021  
Page 3 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04095  
Test: 210310  
Test to: CFR47 15C, RSS-210  
File: A04095 Short Term Conf TSup

SN's: 3361094336, 3361094128  
FCC ID: IPH-04095  
IC: 1792A-04095  
Date: September 20, 2021  
Page 4 of 4