


Internal photographs of equipment under test

Top without Shielding




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA4095  
Test: 210310A  
Test to: CFR47 15C, RSS-210  
File: AA4095 Short Term Conf IntPho

SN's: 3361094106, 3361094128  
FCC ID: IPH-A4095  
IC: 1792A-A4095  
Date: August 27, 2021  
Page 1 of 5

Bottom side




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA4095  
Test: 210310A  
Test to: CFR47 15C, RSS-210  
File: AA4095 Short Term Conf IntPho

SN's: 3361094106, 3361094128  
FCC ID: IPH-A4095  
IC: 1792A-A4095  
Date: August 27, 2021  
Page 2 of 5



Rear Case, PCB removed with shielding



Display rear side



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA4095  
Test: 210310A  
Test to: CFR47 15C, RSS-210  
File: AA4095 Short Term Conf IntPho

SN's: 3361094106, 3361094128  
FCC ID: IPH-A4095  
IC: 1792A-A4095  
Date: August 27, 2021  
Page 4 of 5



## Antenna Locations

