



Test setup photographs




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-01216
Test #: 180321
Test to: 47CFR Parts 2 and 87
File: IPH02256 TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-02256



Date: June 20, 2018
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-01216
Test #: 180321
Test to: 47CFR Parts 2 and 87
File: IPH02256 TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-02256
Date: June 20, 2018
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-01216
Test #: 180321
Test to: 47CFR Parts 2 and 87
File: IPH02256 TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-02256
Date: June 20, 2018
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GMN-01216
Test #: 180321
Test to: 47CFR Parts 2 and 87
File: IPH02256 TSup

SN: 3EG440000, 3EG040007
FCC ID: IPH-02256
Date: June 20, 2018
Page 4 of 4