






882003

FCC ID: IQX98C1995
Mechanical Construction
(Reference Modification No.2)



FCC ID: IQX98C1995
Mechanical Construction
(Reference Modification No.3)




FCC ID: IQX98C1995
Mechanical Construction


882003



FCC ID: IQX98C1995
Mechanical Construction


882003






FCC ID: IQX98C1995
Mechanical Construction
(Reference Modification No.4)¹⁰

882003




FCC ID: IQX98C1995
Mechanical Construction
(Reference Modification No.9・10)

882003





FCC ID: IQX98C1995
Mechanical Construction

882003




FCC ID: IQX98C1995
Mechanical Construction

882003



882003


FCC ID: IQX98C1995
Mechanical Construction
(Reference Modification No.5)



FCC ID: IQX98C1995
Front side of CRT board

Front side of CRT board


882003



882003


995

FCC ID: IQX98C1995
Rear side of CRT board 6-7
(Reference Modification No.6-7)



FCC ID: IQX98C1995
Front side of main Board
(Reference Modification No.11)


882003



FCC ID: IQX98C1995



Rear side of main Board

882003




882003

FCC ID: IQX98C1995
Rear side of main Board




882003

FCC ID: IQX98C1995
Mechanical Construction



882003

FCC ID: IQX98C1995
Front side of USB Board
Reference Modification No.8)



FCC ID: IQX98C1995
Rear side of USB Board

882003