

To Whom It May Concern:

The reason for the permissive change was due to the transmitter integrated circuit being discontinued and changed to a newer one made by the same manufacturer. The new transmitter is cleaner and has less harmonic noise than the old one as can be seen from the test data. Because the parts were not pin compatible, the circuit board was modified in order to accept the part. No other changes were made to the product, and it is functionally the same as the old one.

The only items being submitted are those that have changed since the original submittal:

- Old silk screen
- New silk screen
- Comparison block diagram of old and new RF
- Technical information about the new chip
- New test report
- New photos