## Response to E04-000083-2

- 1. A revised confidentiality letter has been uploade.d
- 2. This information is not required for this device per Randy.
- 3. Our device 6312/6328 is one way system without feedback, it can not and will not adjust its hop table to avoid interference.