




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster

Section 5. Spurious Emissions at Antenna Terminals

Para. No.: 2.1051


Test Performed By: Glen Westwell	Date of Test: June 29, 2001
---	------------------------------------

Minimum Standard: -13dBm


Test Results: Complies.

Test Data: See attached graphs.


EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster




EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster



EQUIPMENT: 48710 & 48722 Signal Booster

