

Hi Greg,

I'm done with the internal/external photos and do you have access to METrak? If you do, here is the link. But if you don't let me know and I'll email you the photos.

\\Santaclarafp\sc_user\EMI\Report\13538 RFS\Internal Photos

For question #1, I think this should have been on 15.209 instead of 15.109. Does it still need to meet the minimum configuration under ANSI C63.4, even if it is suppose to be 15.209? Talked to client and the PC can be connected all of the time but it does not have to be. Mainly use to configure the EUT and to troubleshoot. If this is OK with you, I will ask the technical writer to update the report otherwise retest with minimum configuration under ANSI C63.4.

I'll update the report for the ERP with noted max antenna gain of 1.5dBi.
Also the client is OK with 17.6kHz occupied BW instead of 25kHz.

Do you want the Part 90 report after updating it?

Thanks for the updates.

Kerwinn