## Appendix C. Set up Photograph Conducted Emission

Mode 1



Report No.: FR4N2202-03

**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5
Report Issued Date : Jul. 27, 2005





SIDE VIEW


Mode 2



FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5
Report Issued Date : Jul. 27, 2005





SIDE VIEW

Mode 3




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5
Report Issued Date : Jul. 27, 2005





**REAR VIEW** 




SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5
Report Issued Date : Jul. 27, 2005



## **Radiation Emission**



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C5
Report Issued Date : Jul. 27, 2005