
Appendix C. Setup Photograph Spurious Conduction



Report No. : FR762909

FRONT VIEW



REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Jul. 19, 2007
Report Version : Rev. 01




Side View

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Report Issued Date : Jul. 19, 2007
Report Version : Rev. 01





Spurious Radiation



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Report Issued Date : Jul. 19, 2007
Report Version : Rev. 01