



The following shows an image of the file (image not to scale)



Note:

1. Use related lbl-print file **XXXXXX.LBL**
This file is used to ULTS to create label on a Sato-printer.
Apply the label on the bottom side of the USB foot.
2. Material: Use **59-XXXXXX-00** Blank label.
3. "?????????????" in S/N is variable for Serial Number.

		 Universal Scientific Industrial Co., Ltd.			
		TITLE: ID LABEL FOR USI WAA		SOURCE ORGANIZATION	
		TAIWAN / COM			
		MODEL NO	WAA	DWG NO	XX-XXXXX
			DESIGNER	DATE	UNIT: mm
					USI P/N
		Unless otherwise Tolerance specified ± 2.0	APP BY	DATE	59-XXXXXX-00 1 A2
NO	DESCRIPTION	ReV			