

FCC ID: IYG 702x
EA888802

The 702x and 703x are two different products.... They operate in different frequency ranges:

the correct frequency range for the 702X is: **5150-5350**

Per report number:

TUVR89-A2 Rev A 702X FCC Part 15.407 & RSS-210 Test.pdf

I think the confusion is because the form 731 that was provided by the customer listed all the frequency ranges for both products and I didn't realize that when I submitted the filing on line. But I did send in the correspondence letter that stated the corrected frequency range for this product.

Joyce Nixon