

2007-05-23

- M 2 B

Ref.: FCC ID: IYZFBSB802

Radio equipment authorization to FCC in USA for

FBSB802 (ID-Geber Basis / ID-Geber Keyless Go)

The transmitter will be supplied as an original equipment device to the car manufacturer. According to 47 CFR 15.19 (labelling requirements) the car manufacturer will print the following text in the appropriate User's Manual of the car:

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and

(2) this device must accept any interference received, including interference that may cause undesired operation.

Usually this is followed by the following FCC caution:

Any changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate this equipment.

Rietheim-Weilheim, 2007-05-23

ppa. Dipl. Ing. Karl Müller

pa. Q.60

Marquardt GmbH • Schloss-Str. 16 • 78604 Rietheim-Weilheim • Germany • <a href="http://www.marquardt.de">http://www.marquardt.de</a> Telefon +49 (0) 74 24 - 99 0 • Telefax +49 (0) 74 24 - 99 23 99 • eMail: marquardt@marquardt.de Geschäftsführung: Dr. Harald Marquardt (Sprecher) • Ernst Kellermann • Matthias Marquardt Vorsitzender des Aufsichtsrats: Dr. lng. Hans-Jochem Steim • Amtsgericht Stuttgart HRB 450295