



**M. Flom Associates, Inc. - Global Compliance Center**  
3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176  
[www.mflom.com](http://www.mflom.com) [general@mflom.com](mailto:general@mflom.com) (480) 926-3100, FAX: 926-3598

---

December 12th, 2000

Federal Communications Commission,

Via Electronic Filing

Attention: Frank Coperich

Applicant: TRON Tek Inc.

Equipment: FCC ID: IZ3-TT-2012TS-AB EA98903

Reference: Correspondence 17327 Dec. 11, 2000

Good afternoon Frank:


In reply to the referenced email, please be advised:

Item 1. The original Page 17 shows Occupied Bandwidth without modulation. On original page 18 a 10KHz signal was incorrectly used to modulate the transmitter

Item 2. Photographs: We have alerted our Staff to provide descriptions - and have advised Applicants as well. In this case, the Applicant had provided the photos.

We trust this now completes your requirements.

Personal regards and Compliments of the Season!



MORTON FLOM, P. Eng.

mf;mgf

cc:

cc: Applicant:

c/o jerel@tron-tek.com