



47173 Benicia Street, Fremont CA 94538
Tel: 510-771-1000, Fax: 510-661-0888

Federal Communication Commissions
7435 Oakland Mills Road
Columbia MD 21046

Subject: Request to supersede two files (test report and setup photos)

Ref: Applicant: Qualcomm Inc.
FCC ID: J9CFENWAY-1
Grant date: July 08, 2009

To Whom It May Concern:

Compliance Certification Services (CCS) is the TCB who issued the grant. During the internal audit review, CCS-TCB has found the average output power reported in the test report are wrong due to offset value is not considered. The test lab has revised the test report. However, the peak output power remains unchanged due to peak power was measured with different instruments.

Best Regards

A handwritten signature in black ink, appearing to read 'Mike Kuo', is written over a horizontal line.

Mike Kuo / CEO
Compliance Certification Services
August 13, 2009