
#### **SETUP PHOTOS** 11.

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL LLC.


### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION









# RADIATED RF MEASUREMENT SETUP (BELOW 30 MHz)






TEL: (510) 771-1000 This report shall not be reproduced except in full, without the written approval of UL LLC.


## RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







This report shall not be reproduced except in full, without the written approval of UL LLC.


# RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





# **END OF REPORT**

Page 93 of 93