



HERMON LABORATORIES

November 14, 2005

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated November 10, 2005; Rokonet Electronics Ltd.  
**FCC ID:JE4RK315DT, ATCB002935**

Dear Mr. Johnson,  
Please find below the answers to your questions:

- 1) The internal photographs were removed from the Rokonet's confidentiality letter. The revised file "Confidentiality\_letter\_16528\_rev1" was uploaded on November 14, 2005 via Additional Information folder.
- 2) The file "Schematics\_16528" was uploaded on November 14, 2005.
- 3) Please refer to "Confidentiality\_letter\_16528\_rev1".
- 4) Please classify the file "Operational\_description\_RF\_module\_16528" as confidential.
- 5) The corrected file "Internal\_photographs\_16528\_rev1" with additional photo #6 of the RF module was uploaded on November 14, 2005. There is no any additional circuitry between the antenna and the shield except shown in the PCB photos. Also the RF module is shown in Microwave Solutions data sheet, refer to the file "Operational\_description\_RF\_module\_16528".

Many thanks for your attention to these matters.

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories