



Date: June 4, 2008

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated June 4, 2008; Risco Ltd.  
**FCC ID:JE4RWRT433, ATCB005950**

1. Unfortunately the final photos were lost.
2. First of all a wireless siren has no use if a WisDom panel is not present. If that is indeed the case, the siren will not transmit at all, and not work at all. So the transmitter compliance is also assured as standalone, but must be also considered as part of a system, as HL tested, since the EUT will always be used as part of a system.  
Second if a panel does exist, then each message is sent to that panel and then the siren wait for Acknowledgment.  
[Lack of acknowledgment from the panel, can be considered as "alarm" status, which is cancelled if the Acknowledgment is received in the following 7 retries. So the entire 8 repetitions, can be considered as "during the duration of the alarm" and there for can exceed the 5 sec requirement.](#)
3. The menu is in the panel, but it is setting parameters for siren. If a change in the manual is needed, we will supply draft.

Sincerely,

A handwritten signature in black ink, appearing to read "Efi Goren".

Efi Goren,  
Certification Engineer  
Risco Ltd.