



HERMON LABORATORIES

June 21, 2007

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. R. Fabina, Examining Engineer

RE: your e-mail dated June 20, 2007; Risco Ltd.
FCC ID:JE4RET312PR4, ATCB005043

Dear Mr. Fabina,
Please find below the answers to your questions.

- 1) Hermon Labs confirm that the measured levels of our test report Tables 7.2.3, 7.2.4 and plots 7.2.1 to 7.2.17 include the antenna gain, cable loss and amplifier gain correction factors.
- 2) The error regarding J8 was corrected, see page 9 of the revised file "User_manual_17874_rev1" uploaded on June 21, 2007 via Users Manual folder.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories