


FCC Label



<p>RISCO GROUP</p> <p>Model: RWX35S P/N: RWX35S00900B 915MHz FCC ID: JE4RWX35S915</p>	<p>14 Hachoma St. Rishon Le Zion, ISRAEL</p> <p>Batch date: 01/01/18</p> <p>Replacement of the battery is recommended once a year. Battery Replacement: replace with lithium batteries supplied by RISCO. After replacing the battery check functionality properly using the test button.</p> <p>CAUTION Danger of explosion if battery is incorrectly replaced. Replace detector latest 10 years after DOM (date of manufacturing).</p>	5STN2676
Label		