



Date: 3 April 2014

Attn: Reviewing Engineer  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

To Whom It May Concern:

The Risco Ltd. 433 MHz and 916 MHz RF Module, FCC ID: JE4STAMP433-916, and label are so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,

Motti Barad,  
Certification Engineer  
RISCO Group

A handwritten signature in blue ink, appearing to be "Motti Barad", is located at the bottom left of the page.