

Exhibit: Test Setup Photos

Report File #: 7169006613R-000

© TÜV SÜD Canada Inc. This test report shall not be reproduced except in full, without written approval of TÜV SÜD Canada Inc

Client	Kapsch TrafficCom Canada Inc.	
Product	TRP-8100; Model:802477A-TAB	
Standard(s)	RSS 137 Issue 2 FCC Part 90 Subpart M	SUD



Figure 1 – Radiated Emissions Setup – Photo 1

Page 2 of 4	Report Issued: 9/18/2019	Report File #: 7169006613R-000
-------------	--------------------------	--------------------------------

Client	Kapsch TrafficCom Canada Inc.	
Product	TRP-8100; Model:802477A-TAB	
Standard(s)	RSS 137 Issue 2 FCC Part 90 Subpart M	SUD



Figure 2 – Radiated Emissions Setup – Photo 2

Page 3 of 4	Report Issued: 9/18/2019	Report File #: 7169006613R-000
-------------	--------------------------	--------------------------------

Client	Kapsch TrafficCom Canada Inc.	
Product	TRP-8100; Model:802477A-TAB	
Standard(s)	RSS 137 Issue 2 FCC Part 90 Subpart M	SUD



Figure 3 – Antenna Port Conducted Emissions Setup

Page 4 of 4	Report Issued: 9/18/2019	Report File #: 7169006613R-000
-------------	--------------------------	--------------------------------