



Subject: **Attestation about inactivity of the CDMA2000 BC 10 band**
FCC ID: JUP88161, IC ID: 1756A-88161, Model no. 88161

To whom it may concern

We, Trimble Navigation Limited, do hereby declare that:

The BC10 band capability is disabled by default on the Model 88161 / Geo 7X / GeoExplorer® 7 series.

We confirm that there is no means available to any 3rd party to change this setting.

This is accomplished by the cellular module being supplied with BC10 disabled by the manufacturer and there is no mechanism provided to the user on the device to enable it.

We are aware that enabling of the additional BC10 band would require successful completion of a class 2 permissive change procedure application towards FCC/IC in advance to marketing.

Best Regards,

A handwritten signature in black ink that reads "Bruce Maule".

Name: Bruce Maule
GIS Data Collection Division - Compliance
Company: Trimble Navigation Limited
Address: 935 Stewart Drive, Sunnyvale
California, CA 94085
Date: 23 September 2013
Phone: +1 (408) 481-8000
Fax: +1 (408) 481-7781
Email: Bruce_Maule@trimble.com