


Report No. : FG530302

Appendix C. Set up Photograph

Spurious Radiation



FRONT VIEW

REAR VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 Page No. : C1 of C2 Issued Date : Apr. 26, 2005 Rev. 02





Frequency Stability

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255