

Dear Bill:

Here are the answers.

1. Please check the revised label location.
2. Please check the revised tune up procedure.
3. Please check the revised SAR report.
4. Yes. GPRS can operate in the head or body worn condition, and it will be the worst case.
5. That page is intentional. You could check more info on the first page of SAR report part 2.
6. Please provide voltage and current in final amplifier section as required
by 2.1033(c)(8)
-operation voltage 3.8V current
--GSM900 (level 5) average current 140mA, peak current 1.6A
--DCS1800 (level 0) average current 100mA, peak current 1.4A
--PCS 1900 (level 0) average current 97mA, peak current 1.2A
7. Please check the revised user's manual for this.
8. Please check the revised SAR test report.
9. "Data cable, Earphone, Battery" are the supplied accessories for this product.
10. Please check the revised user's manual.
11. Please check the revised SAR report.

Best regards,
Stephanie