



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 23, 2006

RE: BenQ Corporation

FCC ID: JVPA38

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) Please supply a Manual for this device.
- 2.) Please supply a Label for this device.
- 3.) Kindly look at your Test Report. In section 1.5 you are showing your site was originally listed with FCC in June, 2001. Has this been updated recently with the Commission?
- 4.) Please review Section 3.5 of Test Report. Kindly provide labeling of the X and Y axis of this "Circuit Switched" plot.
- 5.) Please review the calibration records of the SAR measurement system. It appears that the probes were last calibrated in March 2005 and the validation dipoles in June 2004. FCC requires all instrumentation associated with SAR measurements must be calibrated in accordance with the intervals specified in IEEE 1528. This period is specified as one year. Longer times are permitted only if approved by the SAR system manufacturer. Please provide current traceable calibration certificates.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.