

***Conducted Test Setup Placement:***



Front View of the Test Configuration



Side View of the Test Configuration

---


***FCC ID: JVPWL200***

***Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440***

***Radiated Test Setup Placement: (Unintentional)***



Front View of the Test Configuration of unintentional



Rear View of the Test Configuration of unintentional

---


***FCC ID: JVPAWL200***

***Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440***

***Radiated Test Setup Placement: (Intentional)***



Front View of the Test Configuration of Intentional



Rear View of the Test Configuration of Intentional

---

***FCC ID: JVPAWL200***

***Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440***