
## Appendix C. Set up Photograph

## **Spurious Radiation** Model 1



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:

: C1 of C3 Page No. : Jul. 27, 2007 Report Issued Date


Report No. : FG761417A

Report Version : Rev.01

## Spurious Radiation Model 2

FRONT VIEW

**REAR VIEW** 



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:


Page No. : C2 of C3
Report Issued Date : Jul. 27, 2007
Report Version : Rev.01

Report No. : FG761417A

## **Spurious Radiation** Model 3

FRONT VIEW

**REAR VIEW** 



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:

: C3 of C3 Page No. Report Issued Date : Jul. 27, 2007

Report Version

: Rev.01

Report No. : FG761417A