

Appendix C. Set up Photograph

Spurious Radiation Model 1



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:

: C1 of C3 Page No. : Jul. 27, 2007 Report Issued Date Report Version : Rev.01


Report No. : FG761417B

761417

Spurious Radiation Model 2



REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:

: C2 of C3 Page No. : Jul. 27, 2007 Report Issued Date : Rev.01


Report No.: FG761417B

Report Version

Spurious Radiation Model 3

FRONT VIEW

REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID:

: C3 of C3 Page No. : Jul. 27, 2007 Report Issued Date : Rev.01

Report No.: FG761417B

Report Version