



Changes	Before	After
1. RF Band	<ul style="list-style-type: none"> <li>- CDMA (BC0, BC1)</li> <li>- GSM (850, 1900)</li> <li>- GPS</li> </ul>	<ul style="list-style-type: none"> <li>- CDMA (BC0, BC1)</li> <li>- GPS</li> </ul> <p>* By Firmware, GSM functions disabled.</p>
2. Case (Front)		 <p>Navi-Key Rubber design changed.</p>
3. Case (Back)		 <p>SIM insert hole removed. (Inside the case, all related electrical parts remained)</p>