

## Appendix C. Set up Photograph Spurious Radiation



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 

 Page No.
 : C1 of C1


 Report Issued Date
 : Nov. 29, 2005

 FCC ID
 : JYV-V33IG-W-B

 IC ID
 : 4947A-V33IG-W-B


Report No. : FG592703-01

Rev.01





## 1. Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

FCC ID: JYV-V33iG-W-B Page No. : 2 of 4





## 2. Photographs of Radiated Emissions Test Configuration



FRONT VIEW


**REAR VIEW** 



FCC ID: JYV-V33iG-W-B Page No. : 3 of 4







FCC ID: JYV-V33iG-W-B Page No. : 4 of 4