

2101 Tasman Drive Santa Clara, CA 95054 USA tel 408-653-1555 fax 408-567-1069

Modulation Characteristics: FCC Part 24, Subpart D, 24.131

• Test Conditions

The pager was positioned standing on its narrow edge. This position was determined to have the worst case emissions. The HP modulation domain analyzer was configured to have a span of 6.4kHz. A registration transmission which is representative of all transmissions from the pager was captured on the modulation domain analyzer.

• List of Test Equipment

1. Modulation Domain Analyzer, Hewlett Packard, Model No. 53310A, S/N 3105A00303. Calibration date: January 28, 1999. Calibration due date: January 28, 2000.

• Diagram of Test Setup

