

**MFA** M. Flom Associates, Inc.  
Global Compliance Center

3356 N. San Marcos Pl., Suite 107  
Chandler, Arizona 85225-7176  
(480) 926-3100, FAX: -3598  
general@mflom.com  
www.mflom.com

September 20,

Federal Communications Commission,  
VIA Electronic Filing

Attention: Katie Hawkins  
Applicant: Yaesu Musen Co. Ltd.  
Equipment: FCC ID: K66VR-5000 EA97917  
Reference: Corres. 16172 09/19/2000

Item 1. A typical antenna (300 ohm) was connected to the B Port. A set-up photo was supplied to the FCC/. The spurious radiated emission levels were less than previously reported - we report only the worst case.

Item 2. The previous photo showed no ports filled, the AC line conducted test was performed. Again, worst case reported.

Attached is another set of test data with photo.

Item 3. Data previously supplied indicates that this device meets Class B limits and is so stated in Statement of Compliance provided with the submission.

We trust the foregoing now meets your requirements and that the Grant will be issued A.S.A.P.

Personal regards,



MORTON FLOM, P. Eng.

mf;mgf  
encs.

cc: Applicant  
cc: A2LA Corrective Action file