



Intertek Testing Services

ETL SEMKO

Report No.: 03014781
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03014781

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name
21 9k 30M EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03014781
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03014781

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.24000	35.7	62.1
---------	------	------

Frequency	AV Level	AV Limit
MHz	dBuV	dBuV

no Results

* limit exceeded