
FCC TEST REPORT Report No. : FC520402

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : K7SF5D52314
Page No. : 1 of 3

Issued Date : Feb. 04, 2005

FCC TEST REPORT Report No. : FC520402



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : K7SF5D52314

 TEL: 886-2-2696-2468
 Page No.
 : 2 of 3

FAX: 886-2-2696-2255 Issued Date: Feb. 04, 2005

FCC TEST REPORT Report No. : FC520402

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



FCC ID

: K7SF5D52314

REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

TEL: 886-2-2696-2468 Page No. : 3 of 3
FAX: 886-2-2696-2255 Issued Date : Feb. 04, 2005