

Response to E05-000377-2

1. A revised test report has been uploaded showing how the 20.8 db duty cycle correction factor was calculated.