



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 1, 2007

RE: ATCB005423

FCC ID: K9L1030THRX

1. The operational description does not explain anything about the circuitry involved (i.e., please provide operational description, circuitry description of this device).
2. The manual is for a transmitter and has nothing about the receiver in it. Please provide a revised manual.
3. The manual is listed as confidential in the file name but FCC part 15 manuals CANNOT be confidential. Please revise the confidential request letter.
4. Please provide a more detailed block diagram. FCC policy requires that a block diagram show the frequencies of all crystals, VCOs, clocks and other frequency generating circuitry.
5. The schematic seems incomplete, such as we could not find where is the jumper T9 at U1B connect to? Please provide complete schematics.

~~~~~  
~ George Chen  
~ <mailto:george@atcb.com>  
~ Taiwan Mobile: +886 930600123  
~ SKYPE: georghirley  
~~~~~

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.