


Report No.: FR4O1902

Appendix C. Set up Photograph

Conducted Emission



FRONT VIEW


REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3 Issued Date : Feb. 16, 2005








SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3 Issued Date : Feb. 16, 2005



Radiation Emission



FRONT VIEW

REAR VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3 Issued Date : Feb. 16, 2005