

# D-Link®

No.289, Sinhu 3<sup>rd</sup> Rd., Neihu District, Taipei City 114, Taiwan, R.O.C

TEL:+886-2-6600-0123

FRX:+886-2-5550-9988

March 27, 2013

We, D-Link Corporation declare that as part of the DFS functionality in the WLAN driver, software is implemented to react to radar detection messages and move to a new channel. The control of this functionality is not accessible to anyone under any conditions. Furthermore, The firmware only can be modified by using a special tool (console cable) which will not be released and won't supply any console pin with the finish product.

FCC ID: KA2IR855LA1

If you should have any question(s) regarding this declaration, please don't hesitate to contact us. Thank you!



Shinglin Chung / Associate Vice President

Tel: +886-2-6600-0123#5819

Fax: +886-2-5550-9988

E-mail: shinglinchung@dlink.com.tw