



Report No.: TMWK2201000141KR




Report No.: TMWK2201000141KR





Report No.: TMWK2201000141KR



Report No.: TMWK2201000141KR

## UNII-3 IEEE 802.11ax HE20 mode- chain 0

### CH 5785 full



### CH 5785 26/0



### CH 5785 26/8



### CH 5785 52/37



### CH 5785 52/40



### CH 5785 106/53



### CH 5785 106/54



## UNII-3 IEEE 802.11ax HE20 mode- chain 0

### CH 5825 full



### CH 5825 26/8



### CH 5825 52/40



### CH 5825 106/54



## UNII-3 IEEE 802.11ax HE40 mode- chain 0

### CH 5755 full



### CH 5755 242/61



### CH 5795 full



### CH 5795 242/62





Report No.: TMWK2201000141KR

## UNII-3 IEEE 802.11ax HE80 mode- chain 0

### CH 5775 full




### CH 5775 484/65




### CH 5775 484/66



Report No.: TMWK2201000141KR




Report No.: TMWK2201000141KR




Report No.: TMWK2201000141KR



Report No.: TMWK2201000141KR




Report No.: TMWK2201000141KR



## UNII-3 IEEE 802.11ax HE20 mode- chain 1

### CH 5785 full



### CH 5785 26/0



### CH 5785 26/8



### CH 5785 52/37



### CH 5785 52/40



### CH 5785 106/53




### CH 5785 106/54






Report No.: TMWK2201000141KR



Report No.: TMWK2201000141KR



Report No.: TMWK2201000141KR



Report No.: TMWK2201000141KR

**BFM ON- Master**

