



## GoBook III<sup>®</sup> Radio Specific Safety Information

Radio Specific Safety Information

---

### Identification

*GoBook III (IX260+) Radio Specific Safety and Radio Identification Information.*  
June 2004 · Revision Mod July 04

### Copyright Notice

© Copyright 2004 Itronix Corporation. All rights reserved. No part of this document may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any other language or computer language in whole or in part, in any form or by any means, whether it be electronic, mechanical, magnetic, optical, manual, or otherwise, without the prior written consent of Itronix Corporation, South 801 Stevens Street, Spokane, Washington 99204.

### Disclaimer

This document is printed in the U.S.A. Itronix Corporation reserves the right to revise the manual and make periodic changes to the content without a direct or inferred obligation to Itronix to notify any person of such revision or changes. Itronix Corporation does not assume responsibility for the use of this help manual, nor for any patent infringements or other rights or third parties who may use the manual.

This document contains valuable trade secrets and proprietary information of Itronix Corporation.

This product is available for purchase under the terms of the Itronix Hardware Purchase and [Software License Agreement](#). Itronix hardware products may be reconditioned, or be manufactured from parts and components that may be new, used, rebuilt, or recycled and in some cases, the hardware product may not be new and may have been previously installed. In any event, Itronix warranty terms apply.

### Trademark and Patent Notice

Itronix is a registered trademark of Itronix Corporation.  
GoBook III is a registered trademark of Itronix Corporation  
Microsoft, MS, Windows, and MS-DOS are registered trademarks of Microsoft Corporation.  
IBM is a trademark of International Business Machines Corporation.

### Warnings and Safety Information

#### WARNING

It is important that only authorized Itronix personnel attempt repairs on Itronix equipment as this might void any maintenance contract with your company. Unauthorized service personnel might be subject to shock hazard on some Itronix equipment if removal of protective covers is attempted.

Changes or modifications not expressly approved by the party responsible for compliance could void the users authority to operate the equipment.

Internal radio may have an individual FCC Identifier which are not applicable to this configuration. Only the FCC Identifier (KBCIX260PLUSBT) shown on the label located on the bottom of the IX260+ Laptop PC is applicable. The IX260+ Laptop PC must not be co-located or operating in conjunction with any other antenna or transmitter than specified in the filing . This FCC Identifier does not include WLAN and WAN Radios. Cradle option does not support this FCC Identifier.

### Safety Information

This device contains a PAN radio transmitter. When using the PAN transmitter, a minimum separation distance of 20 cm must be maintained between the upper right and left edges of the display screen and all users/bystanders. The PAN transmitter should be turned off before carrying the Laptop PC order to comply with FCC RF exposure requirements.

---

Radio Specific Safety Information  
July 6th 2004