

Responses to Non-Conformities (Ref # E00-000494-1)

Item 1: There is a typo in the labeling statement in condition 2, should say “may caused” not “any caused”. [Section 15.19(a)(3)] There is also a typo in the Users Manual. Notice should state “if **NOT** installed and used in accordance with the instructions, may cause harmful interference to radio communications” or something similar. It currently states “if installed and used in accordance with the instructions, may cause harmful interference to radio communications.” Please see section 15.105(b). Please correct accordingly.

DATE: 10/06/2000 17:25:11 Responses: 1)New label and manual uploaded

Item 2: The 731 form states 11kHz. The block diagram and circuit description does not agree with what is stated on the 731 form. Please correct accordingly.

DATE: 10/06/2000 17:25:11 Responses 2)New block diagram uploaded
Please revise the 731 form to reflect frequency range of .009-.014MHz.

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.