

Radio Systems[®]

C O R P O R A T I O N

4/17/2013

RE: KE3-3002539
2721A-3002539

To whom it may concern:

This is to attest that Radio Systems Corporation will be responsible to make sure the following changes made to the EUT, part number 300-2539, will be applied to all manufactured or marketed products.

These are the changes:

- 1) L4 was added between the AC adapter input and the boost converter circuitry input.
- 2) C43 was added right at the AC adapter power input to the main PCBA.
- 3) L5 was added between the RFID coil driver integrated circuit (U9) and the RFID coil resonant circuit.
- 4) C47 was added between the output side of L5 and ground for the RFID power circuitry.

Sincerely,



Cindy Allen

Product Safety and Regulatory Specialist
Radio Systems Corporation
10427 PetSafe Way
Knoxville, TN 37932
(p) 865-824-5431
www.petsafe.net