

US Tech Test Report:
Issue Date:
Report Number:
Customer:
Model:
FCC ID:
IC:

FCC Part 15.231/ RSS-210
July 30, 2013
13-0211
Radio Systems Corporation
RFA-499 Transmitter
KE3-3002646
2721A-3002646

INTERNAL PHOTOGRAPHS



Figure 1- Cover Removed, Back of PCB

US Tech Test Report:
Issue Date:
Report Number:
Customer:
Model:
FCC ID:
IC:

FCC Part 15.231/ RSS-210
July 30, 2013
13-0211
Radio Systems Corporation
RFA-499 Transmitter
KE3-3002646
2721A-3002646




Figure 2- PCB Removed

US Tech Test Report:
Issue Date:
Report Number:
Customer:
Model:
FCC ID:
IC:

FCC Part 15.231/ RSS-210
July 30, 2013
13-0211
Radio Systems Corporation
RFA-499 Transmitter
KE3-3002646
2721A-3002646




Figure 3- Top of PCB

US Tech Test Report:
Issue Date:
Report Number:
Customer:
Model:
FCC ID:
IC:

FCC Part 15.231/ RSS-210
July 30, 2013
13-0211
Radio Systems Corporation
RFA-499 Transmitter
KE3-3002646
2721A-3002646




Figure 4- Battery Removed