

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018

## INTERNAL PHOTOS





Figure 1. Main Board Front (contains NFC circuitry)

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 2. Main Board Rear (contains NFC circuitry)**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018





Figure 3. Display Board Front

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 4. Display Board Rear**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 5. Internal Mechanism Rear**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 6. Internal Mechanism Left**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 7. Internal Mechanism Right**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15.225 Certification  
KE3-3003450  
2721A-30034501  
24-0201  
10/18/2024  
Radio Systems Corporation  
PAL00-18017 and PAL00-18018



**Figure 8. Internal Mechanism Front**