



**Tune Up Procedure**

Date: December 13, 2019


Subject: Tune Up Procedure for: FCC ID: KE3-3003600, IC: 2721A-3003600

- 1. For licensed devices, Part 95J, the FCC requires a tune-up procedure and a parts list.  
Rule Part 2.1033 (c):

(9) Tune-up procedure over the power range, or at specific operating power levels.

**The RF Transceiver (CC1120) for the Model RAC00-16950 is fully synthesized. There is no factory tuning.**

Sincerely,

By:   
(Signature/Title)

Sandi McEnergy - Agent  
(Print name)