



## Tune Up Procedure

Date: April 15, 2020


Subject: Tune Up Procedure for: FCC ID: KE3-3003643, IC: 2721A-3003643

1. For licensed devices, Part 95J, the FCC requires a tune-up procedure and a parts list.  
Rule Part 2.1033 (c):
  - 2.
- (9) Tune-up procedure over the power range, or at specific operating power levels.

**The RF Transceiver (CC1120) for the Models RAC00-16992, RAC00-16949, RAC00-16952 is fully synthesized. There is no factory tuning.**

*For the MURS radio, testing was done at the default setting of +16 dBm per the Theory of Operation. For the Low Frequency transmitter, the device was programmed to 9.5 which is the maximum setting level for the device.*

Sincerely,

By:   
(Signature/Title)

Sandi McEnergy - Agent  
(Print name)