

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672

External Photographs



Figure 1. Front View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672




Figure 2. Back View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672



Figure 3. Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672



Figure 4. Bottom View 2

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672




Figure 5. Side View 1

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
KE3-3003672
2721A-3003672
22-0139
May 20, 2022
Radio Systems Corporation
300-3672



Figure 6. Side View 2