
## 1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW




REAR VIEW

*SPORTON International Inc.* TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 
 FCC ID
 : KFY-WR1230

 Page No.
 : 1 of 3

 Issued
 : Nov. 14, 2003



SIDE VIEW

*SPORTON International Inc.* TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 
 FCC ID
 : KFY-WR1230

 Page No.
 : 2 of 3


 Issued
 : Nov. 14, 2003

## 1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 
 FCC ID
 : KFY-WR1230

 Page No.
 : 3 of 3

 Issued
 : Nov. 14, 2003